Arrowhead Villas Mutual Service Company

POST OFFICE BOX TT • SKYFOREST, CALIFORNIA B2385 (809) 337-4359 OFFICE • (909) 338-4326 FAX arrowheadvillas@verizon.net

Water Quality Data for 2017

Chemical or Contaminant	Violation Yes/No	Average Level Detected	Range of Levels Detected	MCL	PHG (MCLG)	Typical Source of Contaminant
		PRIM	MARY STANDA	ARDS		
Turbidity (TT)	NO	0.1	.13	0.3	N/A	Soil Runoff
Total Trihalomethanes (uG/l)	NO	6.4	0-24	80	NS	By-product of disinfection
Haloacetic Acids (uG/l)	NO	.65	0-2.4	60	NS	By-product of disinfection
		SECO	NDARY STAND	OARDS		
Chloride (mg/l)	NO	19	15-23	500	NS	Runoff: leaching from natural deposits
Sulfate (mg/l)	NO	10.4	9.7-11.0	500	NS	Runoff: leaching from natural deposits
Total Dissolved Solids (TDS)	NO	210	180-240	1000	NS	Runoff: leaching from natural deposits
		INOR	GANIC CHEMI	CALS		
Aluminum (mg/l)	NO	ND	0	1	0.6	Erosion of natural deposits: residue from surface water treatment processes
Nitrate (as NO3) (mg/l)	NO	1.15	1.0-1.3	45	45	Runoff and leaching from fertilizer use: leaching from septic tanks and sewage: erosion of natural deposits

Chemical or Contaminant	Violation Yes/No	Average Level Detected	Range of Levels Detected	MCL	PHG (MCLG)	Typical Source of Contaminant
		RADIOAC	CTIVE CONTAIN	MINANTS		
Uranium (pCi/l)	NO	6.4	0-17	20	0.43	Erosion of natural deposits
Gross Alpha (pCi/l)	NO	6.6	.4-14	15	0.05	Erosion of natural deposits
		ОТНЕ	ER CONSTITUE	ENTS		
Sodium (mg/l)	NO	9.35	9.1 - 9.6	NS	NS	Erosion of natural deposits
Total Hardness (mg/l)	NO	125	110 - 140	NS	NS	Erosion of natural deposits

Chemical or Contaminant	Required Sampling Frequency	Number of Samples Taken	When all samples should have been taken	When samples were or will be taken
LEAD/COPPER	10 samples every 3 years	10	7/1/2015	7/1/2015